

Monitoring Data Record

Project Title: I-2511CB (I-85 Widening) COE Action ID: 200221534
Stream Name: Town Creek (Site 5) DWQ Number: 040271
City, County and other Location Information: Rowan County, I-85 Widening (-TI-PINC Sta. 20+35)
Date Construction Completed: Water turned on 12/6/06, Stream reforestation completed 12/13/06
Monitoring Year: (4) of 5
Ecoregion: _____ 8 digit HUC unit 03040103
USGS Quad Name and Coordinates: _____

Rosgen Classification: _____

Length of Project: 1,375 Urban or Rural: Urban Watershed Size: _____
Monitoring DATA collected by: M. Green and J. Young Date: 6/28/11

Applicant Information:

Name: NCDOT Roadside Environmental Unit
Address: 1425 Rock Quarry Rd, Raleigh, NC 27610
Telephone Number: (919) 861-3772 Email address: mlgreen@ncdot.gov

Consultant Information:

Name: _____
Address: _____
Telephone Number: _____ Email address: _____

Project Status: Complete

Monitoring Level required by COE and DWQ (404 permit/ 401 Cert.): Level 1 2 3

Monitoring Level 1 requires completion of *Section 1, Section 2 and Section 3*

Monitoring Schedule: The permittee shall perform the following components of Level I monitoring each year for the 5-year monitoring period: Reference photos; plant survival (i.e., identify specific problem areas (missing, stressed, damaged or dead plantings), estimated causes, and proposed/required remedial action); visual inspection of channel stability. Physical measurements of channel stability/morphology will not be required. The permittee shall submit the monitoring reports to the Corps of Engineers, Raleigh Regulatory Field Office Project Manager, within sixty days after completing the monitoring. If less than two bankfull events occur during the first 5 years, the permittee shall continue monitoring until the second bankfull event is documented. The bankfull events must occur during separate monitoring years. In the event that the required bankfull events do not occur during the five-year monitoring period, the Corps of Engineers, in consultation with the resource agencies, may determine that further monitoring is not required. It is suggested that all bankfull occurrences be monitored and reported through the required monitoring period. The permittee shall perform and submit photo documentation twice each year (summer and winter) for the 5-year monitoring period, and for any subsequently required monitoring period.

Section 1. PHOTO REFERENCE SITES

(Monitoring at all levels must complete this section)

Total number of reference photo locations at this site: 5 photo point locations, 2 photos at each location. 2 additional photos were taken as an overview of the buffer area.

Dates reference photos have been taken at this site: 1/23/08, 9/4/08, 2/17/09, 8/10/09, 3/4/10, 9/17/10, 2/9/11, 6/28/11

Individual from whom additional photos can be obtained (name, address, phone): _____

Other Information relative to site photo reference: _____

Section 2. PLANT SURVIVAL

Attach plan sheet indicating reference photos.

Identify specific problem areas (missing, stressed, damaged or dead plantings):

Estimated causes, and proposed/required remedial action:_____

ADDITIONAL COMMENTS: Planted vegetation consisted of black willow and silky dogwood live stakes on the streambanks and tag alder, green ash, red maple, river birch, swamp chestnut oak, willow oak, water oak, tulip poplar, and sycamore bareroot seedlings in the buffer area. The buffer area was replanted with river birch, swamp chestnut oak, and willow oak on 2/29/08 due to lack of planted vegetation. The buffer along the left side downstream of PP#3 was replanted on 3/1/11 with swamp chestnut oak, tulip poplar, and water oak and control access fence was installed to prevent further mowing of the site. NCDOT will continue to monitor vegetation at this stream relocation.

If required to complete Level 1 and Level 2 monitoring only stop here; otherwise, complete section 3.

Section 3. CHANNEL STABILITY

Visual Inspection: The entire stream project as well as each in-stream structure and bank stabilization/revetment structure must be evaluated and problems addressed.

Report on the visual inspection of channel stability. Physical measurements of channel stability/morphology will not be required. Include a discussion of any deviations from as-built and an evaluation of the significance of these deviations and whether they are indicative of a stabilizing or destabilizing situation.

The Town Creek stream relocation is stable for the Year 4 Summer evaluation, except for some bank erosion on the left bank in front of a rock vane at Sta. 16+50 just upstream of the bridge crossing. Some bank erosion was also noted on the right bank at Sta. 13+00 where a drainage ditch exits into the stream relocation. The bank erosion on the right bank at Sta. 13+00 has been noted previously and has seen little or no change since originally noted. NCDOT live staked the eroded areas in March 2010 to help stabilize the banks but the live staking has not stabilized the area.

A site visit was conducted on May 5, 2011 with the regulatory agencies and NCDOT personnel present. It was determined at that meeting that repairs of the left hand bank just upstream of where the bridge crosses was needed. NCDOT plans to use the rock from the rock vane that was installed to construct the toe protection. The bank above the toe protection will be graded at a 3:1 or flatter slope. NCDOT will also plant the repaired area with live stakes during the next planting window (November 15 to March 15). NCDOT will continue to monitor this stream relocation.

| | | | | | |
|--|----------------------------|---|--|--|--|
| Date Inspected 6/28/11 | -TI- PINC Sta. 13+00 | -TI- PINC Sta. 16+50 Additional photo | | | |
| Structure Type | | Rock Structure | | | |
| Is water piping through or around structure? | | | | | |
| Head cut or down cut present? | | | | | |
| Bank or scour erosion present? | Bank erosion on right bank | Bank erosion on left bank | | | |
| Other problems noted? | | | | | |

Section 4. DEBIT LEDGER

The entire Town Creek (Site 5) stream mitigation site was used for the I-2511CB project to compensate for unavoidable stream impacts.

Town Creek



Photo Point #1 (Upstream)



Photo Point #1 (Downstream)



Photo Point #2 (Upstream)



Photo Point #2 (Downstream)



Photo Point #3 (Upstream)



Photo Point #3 (Downstream)

Town Creek



Photo Point #4 (Upstream)



Photo Point #4 (Downstream)



Photo Point # 5 (Upstream)



Photo Point #5 (Downstream)



(Overview looking downstream of buffer area)



(Overview looking upstream of buffer area)

Town Creek



Erosion on right bank @ -TI- PINE Sta. 13+00



Erosion on left bank @ -TI- PINE Sta. 16+50

Year 4 Summer – June 2011

8/12/91

I-2511CB

Town Creek
Photo Point Locations



| | |
|---------------|---------------|
| Photo Point 1 | Photo Point 2 |
| Photo Point 3 | Photo Point 4 |
| Photo Point 5 | |




Photo Point 1

Photo Point 2

Photo Point 3

Photo Point 4

Photo Point 5

HPA ENGINEERING
MA Engineering
10000 1st Avenue SW
Burien, WA 98148
206-835-1100
FAX 206-835-1101
www.hpa-engineering.com

PAVEMENT REMOVAL
FOR POINTS SEE SHEETS 22, 31, 3

ROADWAY PLANS